

**MINE INSPECTION REPORT - PERMANENT PROGRAM** Hand Delivered? **898-0619**

<b>Company Name and Address</b> CAMBRIAN COAL CORPORATION P O BOX 100 BELCHER, KY 41513	Acres Permitted	567.46	Status	AP	Start Time	08:00 AM	End Time	03:00 PM
	Mine Type	Acres Bonded	Inspection Date		Type			
	SURFACE	592.86	07/29/2010		P			
	Weather	Est. Acres Disturbed						
	LIGHT RAIN	325						

Insolvent Surety	Photos	Reasons For Inspection	Overall Site Condition	Est. Acres Reclaimed	End Inspection Date
No	Yes	CR		100	07/29/2010

Non-Compliance	Cessation Order Number	Cessation Order Type	INC/ICO Number	INC/ICO Type	IAO Number	IAO Type	Modification Number	Modification Type	Permit Expiration Date
53-1556									1/22/2009

(SM)	Signs and Markers KAR 16:030 or 18:030	(SC)	NC	Sedimentation Ponds KAR 16:090 or 18:090	(SS)	Steep Slopes KAR 20:060
(AC)	Roads KAR 16:220 or 18:230	(DV)		Diversions KAR 16:080 or 18:080	(MR)	Mountaintop Removal KAR 20:050
(TH)	Topsoil KAR 16:050 or 18:050	(WQ)		Water Quality KAR 16:070 or 18:070	(AM)	Auger Mining KAR 20:030
(UE)	Use of Explosives KAR 16:120 or 18:120	(HR)		General Hydrologic Requirements KAR 16:060 or 18:060	(PF)	Prime Farmland KAR 20:040
(DS)	Disposal of Excess Spoil KAR 16:130 or 18:130	(WM)		Water Monitoring KAR 16:110 or 18:110	(PP)	Processing Plants KAR 20:070 or 20:080
(BG)	Backfilling and Grading KAR 16:190 or 18:190	(IM)		Impoundments KAR 16:100 or 18:100	(PL)	Post-Mining Land Use KAR 16:210 or 18:220
(CR)	Contemporaneous Reclamation KAR 16:020 or 18:020	(WD)		Coal Waste Dams KAR 16:160 or 18:160	(DH)	Drilled Holes KAR 16:040 or 18:040
(OF)	Other Facilities KAR 16:250 or 18:260	(DC)		Disposal of Coal Processing Waste KAR 16:140 or 18:140	(UO)	Approved Operator KAR 8:010
(DW)	Disposal of Non-Coal Waste KAR 16:150 or 18:150	(AP)		Air Resources Protection KAR 16:170 or 18:170	(OC)	Ownership and Control KAR 8:010
(RV)	Revegetation KAR 16:200 or 18:200	(FW)		Fish and Wildlife Protection KAR 16:180 or 18:180	(SB)	Subsidence KAR 18:210
(OD)	Off Permit Disturbance KAR 7:040	(OO)		Mining Off Permit U/G KAR 7:040 or 8:010	(OT)	Other Permit Conditions
(OM)	Method of Operation KAR 08:010	(LI)		Liability Insurance KAR 10:030	(SF)	Surety Failure KAR 10:030
(EL)	Effluent Limitations KAR 5:065	(FR)		Flyrock KAR 16:120	(SW)	Surface and Ground Water KAR 16:110, 18:110, or 5:065

Describe all changes since last inspection, including change in operator or contractor and name(s) of any person(s) who accompanied you during this inspection (citizen, chief, other federal or state inspectors); etc.

Complete inspection - All structures with KPDES sampled and in compliance. Yes  No  If Yes not selected, list points in violation.

**Non-Compliance 53-1556 issued this date in conjunction with CRI 10-05-0150. This inspection and non-compliance replaces non-compliance 53-2472 which was written in error on permit number of 898-0819 and will be vacated from that permit.**

Env. Inspector:	<i>Gene Blackburn</i> Gene Blackburn	I.D. No:	050298	Date:	08/10/2010
Env. Control Supervisor:				Date:	
Env. Control Manager:				Date:	
Person On-Site To Whom Copy Was Delivered:		Signature:			
Person To Whom Copy Was Hand Delivered:		Signature:			
Certified Mail No.		Certified Date			
Contact Inspector at:	gene.blackburn@ky.gov 606-433-7726				
Copies Mailed To:	CAMBRIAN COAL CORPORATION 15888 FERRELLS CREEK RD P O BOX 100 BELCHER, KY 41513				

Permittee Name: CAMBRIAN COAL CORPORATION

I.D. # 013154

An inspection conducted on 07/29/2010 revealed that permit 898-0619 is in violation of approved provisions and/or regulations. The extent of the violation(s) and or remedial action(s) is as follows:

1 Code SC Regulation/Performance Standard Sedimentation Ponds - KAR 16:090

Permittee responsible for violation

Permittee and operator \_\_\_\_\_ ID#: \_\_\_\_\_ responsible for violation.

Description of violation and location:

The sediment level in sediment structure #SS-39 has exceeded the approved elevation as set forth in the permit plan below Hollowfill #9 on increment 22.

Violation occurred on Increment # 22 Bonded by Surety Name: EVERGREEN NATIONAL COMPANY ID#: 0845

Violation Correctable - Remedial Measures to be performed:

Remove the sediment from sediment structure #SS-39 and dispose of it according to your approved plans.

You are ordered to correct the above violation by 4:00 p.m. on 08/09/2010.

Violation Non correctable - Because:

Code  Regulation/Performance Standard

Permittee responsible for violation

Permittee and operator \_\_\_\_\_ ID#: \_\_\_\_\_ responsible for violation.

Description of violation and location:

Violation occurred on Increment # \_\_\_\_\_ Bonded by Surety Name: \_\_\_\_\_ ID#: \_\_\_\_\_

Violation Correctable - Remedial Measures to be performed:

You are ordered to correct the above violation by \_\_\_\_\_ on \_\_\_\_\_.

Violation Non correctable - Because:

Env. Inspector:

*Gene Blackburn* Gene Blackburn

I.D. No:

050298

Date:

08/10/2010

Env. Control Supervisor:

Date:

Env. Control Manager:

Date:

Person On-Site To Whom Copy Was Delivered:

Signature:

Person To Whom Copy Was Hand Delivered:

Signature:

Certified Mail No.

Certified Date

Contact Inspector at:

gene.blackburn@ky.gov 606-433-7726

upon completion of remedial measures

File	8980619-NC531556-SC	Date	07/29/2010
------	---------------------	------	------------

Permit / Project	CAMBRIAN COAL CORPORATION	Number	898-0619
------------------	---------------------------	--------	----------

Comment	
---------	--

Inspector	
-----------	--



Photo depicts Pond #SS-39 exceeding cleanout capacity.

--	--